Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 of 2
Property ID: 4639-45-6720
Lot #: 6
File #: 143705
AppID:

gm

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

Owner: Dave Liberatore
Address:
Proposed Facility: SFR Design Flow (.1949) 480 GPD
Location of Site: 125 Hawksnest Lane
Water Supply: [ ] Public [x] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [x] Auger Boring [x] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

Applicant: Same
Date Evaluated: 5/6/2010
Property Size: 1.63 AC
Property Recorded: Yes

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941		b PROFILE FACTORS				Profile Class & LTAR
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	
PIT	LINEAR	0-24	RC,SBK	SS,SP,SEXP	NA				
#1	8-12%	24-48	RCL,M,F,SBK	SS,SP,SEXP	NA				
		48-65	LSAP,MASS	SS,SP,SEXP	NA	48"	PS	NA	.3
PIT	SIDE	0-8	WK,SBK,SCL	SS,SP,FR	NA				
#2	16%	8-16	M,SBK,C	SS,SP,FR	NA				
		16-26	WK,SBK,CL	SS,SP,FR	NA				
		26-46	WK,SBK,CL	SS,SP,FR	Y/R				
		46-55	LSAP,MASS	SS,SP,FR	NA	46"		NA	.3
PIT		0-8	GR,CL	SS,SP,FR	NA				
#3		8-28	MO,SBK,RC	SS,SP,FR	NA				
		28-45	MO,F,SBK,CL	SS,SP,FR	NA				
		45-60	SLSAP,MASS	SS,SP,FR	NA	56"		NA	.3
PIT		0-9	GR,B,SL	SS,SP,FR	NA				
#4		9-39	SBK,RC	SS,SP,FR	NA				
		39-56	MO,F,SBK,CL	SS,SP,FR	NA				
		56-67	SLSAP,MASS	SS,SP,FR	NA	56"		NA	.3

Description	Initial System	Repair System
Available Space (.1945)	PS	PS
System Type(s)	G-25%	G-25%
Site LTAR	.3	.35

Other Factors (.1946):
Soil Evaluation By: BS,DH,JM,AR
Others Present:
Site Classification (.1948):
Site Evaluation By: BS,DH,JM,AR
Others Present: