IREDELL COUNTY HEALTH DEPARTMENT

STATESVILLE 704-878-5305 MOORESVILLE 704-664-5281

IMPROVEMENT PERMIT / AUTHORIZATION TO CONSTRUCT / OPERATION PERMIT / EXISTING SYSTEM INSPECTION

PERMIT# 143707 PIN# 4639 55 0682.007 4639-45-7784 DATE August 21, 2007

OWNER OR APPLICANT Tegland-Brown Construction, Inc. / Mike Jeong PHONE: Business _____ Home _____

ADDRESS 1950 Weavers Circle, Connelly, N.C. 28031

LOCATION Perth Rd. (N) TR FERN Hill Rd. TR Hawks Nest Cr. on left in cul-de-sac

SUBDIVISION Woodstream Estates BLOCK / SECTION _____ LOT 7 LOT AREA 1.12Ac+.5Ac SFE SITE CLASS. PS SFE DESIGN FLOW 480gpd L.T.A.R. .3 SFE

Septic Tank 1000 Gallons: STB 312 Date 9-3-07

Pump Tank 1000 Gallons: PT 27 Date 2-2-08

Pump Make Gould's Model WI=0112H Serial No _____

Nitrification Field No Fields 1 Square Feet 1200 Linear Feet 400

No Lines 4@100' Trench Width 36" Max Trench Bottom Depth 36" Gravel Depth NA ☐ Gravity ☒ Pressure ☐ Slab ☐ Crawl Space ☒ Basement w/plumbing ☐ Basement wo/plumbing

☒ New System ☐ Repair ☐ Expansion System Type: I II III IV V VI

System Description: PM 25% Reduction Offsite

Repair System Description: LS PUMPS

Maintenance Agreement Required: ☐ Yes ☒ No

☒ House/Mod. Home ☐ Mobile Home ☐ Business ☐ Other

No. Bedrooms 4 No. Persons ___ No. Employees ___

Water Supply: ☒ Individual ☐ Public ☐ Community

Comments/Conditions 4/16/08 Reviewed Floor plans & Site plan in Compliance with original permit. (House bigger than originally drawn but Septic & Drainfield going off site)

INITIAL SITE SKETCH

SEE Plan from Rollins Soil + Env. Services

Comments/Conditions: 11/25/08 Checked Drainfield Quick LF Installed

10/3/08 Press (2ft) Elect & alarm

AS BUILT SKETCH

The proposed / existing Adding Bedroom to Basement addition does not appear to impact the existing septic system.

**NOTE: Original Septic permit had 4 Bedrooms & only 3 were Built

Maria A. Dolan REHS

Date: 9/29/2010

ICHD-Environmental Health Division

Permit can be suspended or revoked if any false information is supplied toward securing the permit/any unauthorized changes are made to the site/any unauthorized changes are made in the installation of the system. Improvement Permit with plat valid without expiration ☐ Improvement Permit with site plan valid for sixty months ☒ Authorization to Construct is valid for a period equal to that of Improvement Permit - not to exceed sixty months.

Signed: Mike Jeong date 8-22-07 Installed by: Richard Thornton

Improvement Permit by: _____ date 8-21-07 Operation Permit by: Maria A. Dolan date 10/3/08

Authorization to Construct by: Maria A. Dolan date 4/16/08 Existing System Inspection by: _____ date _____

HEALTH DEPT. COPY: WHITE OWNER COPY (FINAL): YELLOW OWNER COPY (INITIAL): PINK