
L69
L68
L67
L66
L65
L64
L63
L62
L61
L60
L80
L46
50' BUFFER
35.71'
9.68'
13.68'
190.04'
305.94'
348.52'
260.39'
18
30445 SF
0.70 AC.
19
34465 SF
0.79 AC.
20
43138 SF
0.99 AC.
60²
DRIVE
104.57'
L=99.37'
L=78.30'
L=41.57'
L=141.26'
L=196.43'
R=590.66
L=120.07'
L=69.70'
L=63.15'
L=123.19'
35' FRONT YARD
49.97'
152.08'
214.47'
COVE TRAIL
PUBLIC R/W
5
4
3

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 19 Bay crossing PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	BSCL wksmk	fri SSSP					PS -3
		6-40	RC/CL mksmk	fri SSSP					
		40-52	YRCL wksmk	fri SSSP-fw SOP					
2		0-6	BSCL vfgrnk	fri SSSP					PS -3
		6-32	RC SCL	fri SSSP					
		32-46	YRCL wsmk	fri SSSP					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____