4639 69 9792

375.00 Paid

IREDELL COUNTY HEALTH DEPARTMENT

STATESVILLE 704-878-5305 MOORESVILLE 704-664-5281

IMPROVEMENT PERMIT / AUTHORIZATION TO CONSTRUCT / OPERATION PERMIT / EXISTING SYSTEM INSPECTION

PERMIT# 129524 PIN# 4730 10 5378 704-696-2662 DATE 7/21/06

OWNER OR APPLICANT BO of NC/Hunter Homes PHONE: Business 704-489-4663 Home

ADDRESS 5734 Hwy 150 East Denver, NC. 28037 / 249 Wellington Rd.

LOCATION 150 W TR Perth Rd. Tr Winding Front. lot 10 on (L), then on Agnes

SUBDIVISION Winding Front BLOCK / SECTION LOT 10 LOT AREA 1.23 Ac SITE CLASS. PS DESIGN FLOW 480 L.T.A.R. .25

Septic Tank: 1000 Gallons; STB 350 Date 12/14/06
Pump Tank: 1000 Gallons; PT 318 Date "
Pump Make: See Spec Sheet Serial No.
Nitrification Field: No Fields 1 Square Feet 1035 Linear Feet 345
No Lines 6 Trench Width 3' Max Trench Bottom Depth 36"

☒ New System ☐ Repair ☐ Expansion System Type: I II III IV V VI
System Description: LP-16" PPBPS
Repair System Description: SAME TYPE
Maintenance Agreement Required: ☒ Yes ☐ No

☒ House/Mod. Home ☐ Mobile Home ☐ Business ☐ Other
No. Bedrooms 4 No. Persons 8 No. Employees

Water Supply: ☐ Individual ☐ Public ☒ Community

Gravel Depth NA ☐ Gravity ☐ Pressure ☐ Slab ☒ Crawl Space ☐ Basement w/plumbing ☐ Basement wo/plumbing

Comments:/Conditions: FAST TRACK & ROLLANS ENVIRONMENTAL ACCEPTABLE FOR PRESSURE DOSED 16" PPBPS LOCATION AS SHOWN ON SITE PLAN + DRAINFIELD AREA SHEET.

Comments:/Conditions: Move Front House Corner to 15' Setback

INITIAL SITE SKETCH

ROLLANS ENVIRONMENTAL

PLANS & SPECS REQUIRED BEFORE INSTALLATION STARTED.

House Plan Review Required!

AS BUILT SKETCH

Drainlines checked 5/18/07 } by Hurley
Tanks checked 5/18/07 }
Valve Box checked 5/18/07 } Sparks

Pressure Head SRT
Floats & pump checked 2/15/08 by Anthony Cates

Need electrical Inspection and a Maintenance Contract before issuance of O.P.
AC.

Permit can be suspended or revoked if any false information is supplied toward securing the permit/any unauthorized changes are made to the site/any unauthorized changes are made in the installation of the system. Improvement Permit with plat valid without expiration ☐ Improvement Permit with site plan valid for sixty months ☐ Authorization to Construct is valid for a period equal to that of Improvement Permit – not to exceed sixty months.

Signed: x Duane Laudlaw date 7-24-06 Installed by: Piedmont Septic Tanks REHS 7/14/2010

Improvement Permit by: Wesley Sparks RS, date 7/21/06 Operation Permit by: Maria H. Dotson date

Authorization to Construct by: Joseph E. Allen date 10/24/06 Existing System Inspection by: date

HEALTH DEPT. COPY: WHITE OWNER COPY (FINAL): YELLOW OWNER COPY (INITIAL): PINK

4639 69 9792

3745.01

8/29/07

ALTH DEPARTMENT
T / AUTHORIZATION TO CONST

PIN# 4730 10 5378

O of NC / Hunter's Manor
150 East Denver, NC. 28
South Rd. ft Winding Fo

BLOCK / SECTION ____ LOT 10 LOT AREA ____

STB 3513 Date 12/14/06 ☒ New System
T 3/8 Date ____ System Descrip
Sheet Serial No. ____ Repair System
Feet 1035 Linear Feet 345 Maintenance Ag
3' Max Trench Bottom Depth 36" Gravel D

TRACK & ROLLANS ENVIRONMEN
PRESSURE DOSED 16" PPBAS
WN ON SITE PLAN + DRAINFIEL

Drain Lines Checked	
Tanks Checked	
Pressure Manifold or Valve Box Checked	
Pressure Head Set	
Electrical Checked Not yet	
Floats Set	
Alarm Checked	
Maintenance Contract (Y) N	

Per Kelly, They can drill individual wells as long as they can meet set backs. ME

INITIAL SITE SKETCH

ENVIRONMENTAL
FICS. REQUIRED BEFORE
STARTED.

Review Required!

AS BUILT SKETCH

Drainlines checked 5/18/07 } by Wesley
Tanks checked 5/18/07 }
Valve Box checked 5/18/07 } Sparks

Pressure Head Set 2/15/08 by Anthony Coker
Floats + pump checked

vInspection
Need electrical and a Maintenance Contract before issuance of O.P.
AC.

y false information is supplied toward securing the permit/any unauthorized changes are made to the site/any unauthorized changes are made in the installation of the system. Improvement
] Improvement Permit with site plan valid for sixty months ☐ Authorization to Construct is valid for a period equal to that of Improvement Permit – not to exceed sixty months.

Loudlaw date 7-24-06 Installed by: Piedmont Septic REHS 7/14/2010
Lofland RS. date 7/21/06 Operation Permit by: Maria Dotson date
ME Cofer date 10/24/06 Existing System Inspection by: date

HEALTH DEPT. COPY: WHITE OWNER COPY (FINAL): YELLOW OWNER COPY (INITIAL): PINK