DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

# SOIL/SITE EVALUATION
## for ON-SITE WASTEWATER SYSTEM

OWNER: Heidt Properties Inc. APPLICANT: ___
ADDRESS: ___ APPLICATION DATE: ___ DATE EVALUATED: 2/6-05
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 480gpd PROPERTY SIZE: ___
LOCATION OF SITE: Lot 58 Bay Crossing PROPERTY RECORDED: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

| PROFILE # | .1940 LANDSCAPE POSITION/ SLOPE % | HORIZON DEPTH (IN.) | SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE | .1941 CONSISTENCE/ MINERALOGY | OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR | .1943 SOIL DEPTH | .1956 SAPRO CLASS | .1944 RESTR HORIZ | PROFILE CLASS & LTAR |
|---|---|---|---|---|---|---|---|---|---|
| 1 | | 0-2 | | | | | | | .3 |
| | | 2-21 | wkfSBKRC | fr sssp | | | | | |
| | | 21-55 | wkfSBKRcl | fr sss/p common wksap 32% | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 2 | 15% L | 0-16 | SBK RC | fr sssp | | | | | .3 |
| | | 16-48 | wkSBK Rcl | fr sssp common wksap | | | | | |
| | | 48-52 | massive LSPA | fr sss/p | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 3 | 3-9-05 | 0-6 | wkSBK SL | fr sssp | | | | | .3 |
| | | 6-30 | SBK RC | fr sssp few fine mica inf. | | | | | |
| | | 30-54 | SBK Rcl | fr sssp few fine mica sap | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| 4 | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |

| DESCRIPTION | INITIAL SYSTEM | REPAIR SYSTEM |
|---|---|---|
| Available Space (.1945) | PS | PS |
| System Type(s) | Conv 25% Red | SAME |
| Site LTAR | .3 | .3 |

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: DHutchinson, RS
OTHER(S) PRESENT: Kathleen, TCJ