Sheet:
Property ID:
Lot #:
File #:
AppID:

CCSC SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Meritage Homes
Address:
Applicant:
Proposed Facility:
Date Evaluated:
Location of Site: Bells Crossing Subdivision, Lot 81
Design Flow (.1949)
Property Size:
Property Recorded:
Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [X] Auger Boring [ ] Pit [ ] Cut
Type of Wastewater: X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
#1	LS, 9%	A, 0-15	Gr, SL	VFR, NS, NP	7.5 YR 4/6				
	Old Road Bed	Bt1, 15-30	SBK, SCL	FR, NS, NP	7.5 YR 4/6	PS			PS, 0.4
		Bt2, 30-44+\	SBK, Clay	FI, SS, SP	5 YR 4/6	PS			PS, 0.3
#2	LS, 9%	A, 0-12	Gr, SL	VFR, NS, NP	7.5 YR 4/6				
		Bt1, 14-36	SBK, Clay	FI, SS, SP	5 YR 4/6	PS			PS, 0.3
		Bt2, 36-44+	SBK, Clay Loam	FI, SS, SP	5 YR 4/6	PS			PS, 0.3
#3	LS, 9%	A, 0-8	Gr, SL	VFR, NS, NP	7.5 YR 4/6				
		Bt, 8-44+	SBK, Clay	FI, SS, SP	5 YR 4/6	PS			PS, 0.3

Description	Initial System	Repair System
Available Space (.1945)	Yes	Yes
System Type(s)	Accepted	Accepted
Site LTAR	0.3	0.3

Other Factors (.1946):
Soil Evaluation By: Jason Hall
Others Present:
Site Classification (.1948):
Site Evaluation By:
Others Present:

