...DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 12-27-02
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 42 Creek wood PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut Need pits in front
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	10/5 below Old Berm Remnant	0-14	gr brn scl	frssp					.225-.25 @ 24"/36
		14-36	wk fsbk pbrn c	fr sp					
		36-50	m f-m ms red/gl	fr sp-ssp	common gl/wh mottles				
			a little water bleeding out @ the beginning of this horizon		probably due to LS pos. vs berm				May need Fill Dry in
2		0-12	wk sbk brn scl	frssp					.225-.25
		12-49	wk f sbk/ms pbrn-R c	fi sp					
			Pale brn mottles, few in		sapro small pockets rock 74"				
3	2-24-03	0-5	wk sbk brn scl	frssp					.25
		5-29	m f sbk rc	fr sp ssp					
		29-53	wk sbk gr/cl	frssp Red common mi/sp					
4	2-24-03	0-7	gr-wk sbk brn scl	frssp					.25-.3
		7-46	m f sbk rc	fr sp					
		46-66	wk f sbk gr/cl	fr ssp fri mi sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____