DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ____ *of* ____
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Tim Blackwelder APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: 7/12
PROPOSED FACILITY: House PROPOSED DESIGN FLOW (.1949): 480 PROPERTY SIZE: _____
LOCATION OF SITE: Lot 15 Creekview & Village PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	CV LS 3-5	0-7	SBK / l	FI SS-MP	PS / BR				
		8-28	few GR SBK / c	FR SS-SP	PS / R				
		29	ROCK / TERM.						
2	nCC L 5-5	0-6	GR / l	FR SS-SP	PS / BR				
		7-21	few ABK SBK / c	FR S-SP	PS / R				
		22-29	M SBK / cl	FR SS-SP	PS / 4R				
		30	QUARTZ ROCK / TERM.						
3	CCL 3-5 IER.	0-8	GR / cl	FI SS-SP	PS / B				
		9-27	few ABK SBK / c	FR SS-SP	PS / R				
		28-39	MF SBK / cl	FR SS-SP	PS / R				
		40-49	F SBK / cl	VFR SS-SP	PS / R 4R INCL.				.3
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____