Sheet:
Property ID:
Lot #:
File #:
AppID:

CCSC SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Meritage Homes
Applicant:
Address:
Date Evaluated:
Proposed Facility: Design Flow (.1949)
Property Size:
Location of Site: Bells Crossing Subdivision, Lot 87 Septic Easement
Property Recorded:
Water Supply: [X] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [ ] Auger Boring [X] Pit [ ] Cut
Type of Wastewater: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
Pit 10	R, 3-5%	Bt, 0-45	SBK, Clay	FI, SS, P	2.5 YR 4/8	PS			PS, 0.3
					7.5 YR 5/8, 5%				
		BC, 45-53	Wk SBK, SCL	FR, SS, SP	2.5 YR 4/8	S			S, 0.35
Pit 12	R, 3-5%	Bt1, 0-37	SBK, Clay	FI, SS, P	2.5 YR 4/8	PS			PS, 0.3
		Bt2, 37-48	SBK, Clay	FI, SS, P	2.5 YR 4/8	S			S, 0.3
					2.5 YR 8/2, 10%				
					Relic				
		Bt3, 48-54	SBK, SCL	FR, SS, SP	2.5 YR 4/8	S			S, 0.35
					2/5 YR 8/2, 10%				
					Relic				

Description	Initial System	Repair System
Available Space (.1945)		Yes/ off-site
System Type(s)		Accpted or T & J
Site LTAR		0.3

Other Factors (.1946):
Soil Evaluation By: Jason Hall
Others Present:
Site Classification (.1948):
Site Evaluation By:
Others Present:

