SOIL/SITE EVALUATION

(Continuation Sheet)

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

Bells Crossing Lot #

Sheet ___ of ___

PROPERTY ID #: _____
DATE OF EVALUATION: _____
COUNTY: _____

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
P	55	0-9	B SCL Gr	55, SP, Fr SExP	28" Chr 2	48"	—	28"	PS
206	0-5%	9-24	RB C WMABk	55, SP, Fr SExP	com/many YB				
A		24-32	RYC WFSBk/ABk	55, SP, Fr SExP	com/many YB few chr 2				
		32-48	R CL WFSBk	55, SP, Fr SExP	com Chr 2 32-40" few → 40"				.1 appl drip
P	Terrace	0-16	DP SL Gr	55, SP, Fr SExP	Chr 2 40"	50"	—	40"	PS
206	0-5%	16-22	BR SCL VWFSBk	55, SP, Fr SExP					
B		22-30	YR C VWFSBk	55, SP, Fr SExP	few YB, few Mn, com Fe concentrations com/many YB >40" few Chr 2 +Mn				.2 to 40"
		30-50	R C VWMSBk	S, P, Fi SExP					
P		0-5	B sl-scl gr	Fr SS SP SExP					
206		5-24	YR C VMABk	F SS P SExP	- CYB's - C Reds - chr 2's - CYB's, FSexp - fYB's, CSexp				
C	4/0-5	24-38	R C VW MSBk/ABk	F SS SP SExP		55	-	24"	PS
		38-55	R Cl VW MSBk	F SS SP SExP					0,1 drip
P		0-9	YR scl gr-MSBk	Fr SS SP SExP					
206		9-18	BR SC WMABk/SBk	Fr SS SP SExP					PS
D	4/0-5	18-43	RB C VWMABk/SBk	F SS SP SExP	- MYB's - f chr 3/4's - stone line @ 55" - CSexp - fc YB's	54	—	—	0,2
		43-54	RYscl VWSBk	Fr SS SP SExP					

COMMENTS: _____