4639882296

10237

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charlie Clontz DATE Sept. 5, '89 PERMIT NO. 3F-A-13

PHONE: Business _____ Home _____

LOCATION 1303 N. TR 1300 (Fern Hill Rd.) 3rd home on Right (1/4 mile) S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

Remodeling – Enlarging bedroom, basement, adding bath


House (✓) Mobile Home ( ) Business ( ) Other System replacement w/Addn

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay
Auto. Dishwasher	Yes ( )	No (✓)	Percolation Rate	4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	6-8%
Site ~~Suitable~~ PS	Yes (✓)	No ( )	Depth to Water Table	4'
			Rock or other impervious formations	none obs.

Lot Area acreage

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓ Ex.
Public ( )

Installed by D. Lackey

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: SR 1300

CERTIFICATE OF COMPLETION BY _____ DATE Sept 5, '89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

2500

10237

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Charlie Clontz DATE July 24, '89 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1303 N. (Perth Rd.) TL 1300 (Fern Hill Rd.) 3rd house on Right (~1/4 mile) S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

Remodeling - Enlarging bedroom, adding bath

House (✓) Mobile Home ( ) Business ( ) Other System replacement w/ Addn.

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes ( ) No (✓)

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area acreage

Character & Porosity of Soil clay


Percolation Rate ~.4

Topography 2-10%

Depth to Water Table 4'+

Rock or other impervious formations none obs.

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3-4
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓ Existing)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed Charlie T Clontz

IMPROVEMENTS PERMIT BY Claire R. Hunsucker, RS

COMMENTS: Follow contour with drainfields. No drainfield line deeper than 36" to trench bottom. Use drop boxes to distribute effluent.
Remove old tank and drainfield at least 15' from basement wall.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold