4639882296

IREDELL COUNTY HEALTH DEPARTMENT

10528

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Dwight Clontz DATE 10/3/90 PERMIT NO. 3F-A-12

PHONE: Business _____ Home _____

LOCATION 1303 N. TL 1300 (Fern Hill Rd) N ¼ mi on right
2nd house on right. S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

Remodeling old house + making addition

House (✓) Mobile Home ( ) Business ( ) Other System replacement

No. Bedrooms 3 No. Bathrooms 2


Garbage Disposal Unit	Yes (✓)	No ( )	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable?	Yes ( )	No ( )	

Lot Area _____

Character & Porosity of Soil clay
Percolation Rate ~ .4
Topography 15%
Depth to Water Table 4' +
Rock or other impervious formations none obs

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement (X)

+100' New Well



Plot of System SR 1300

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Larry Beam

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: ~260' Sch 40 4" Pipe

CERTIFICATE OF COMPLETION BY Sam Ongram EHS DATE 10/3/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold