ON-SITE WASTEWATER SECTION

COUNTY:

SOIL/SITE EVALUATION

NAME: Vanderbilt West APPLICANT:

ADDRESS: APPLICATION DATE: DATE EVALUATED: 8/6/2011

PROPOSED FACILITY: PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:

LOCATION OF SITE: Neil Farm Rd PROPERTY RECORDED:

WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other

EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-18"	Brw SCL GR FR						PS
		18-30	Rd/Brn to Brn C/CL SBK to		18" S-SS	SP SE FI FR			
		30-48	Rd/Brn to Yel/Brn SC/SCL w/ Mottles Chroma 2		w/ few to many Yel/Brn mottles at 30"				.25 to .2
			May be	"Tiger stripe"					
2		0-12"	Brn SCL GR FR						PS
		12-48"	Rd/Brn C/CL SBK		S-SS, SP SE FI-FR				.25 to .3
			w/ Few Yel/Brn		Mottles				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
(System Type(s))		

OTHER FACTORS (.1946):

SITE CLASSIFICATION (.1948):

EVALUATED BY:

OWNER(S) REPRESENTATIVE:

2 of 2