DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Krow APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 11-28-95
PROPOSED FACILITY: SFR PROPOSED DESIGN FLOW (.1949): 360gpd PROPERTY SIZE: _____
LOCATION OF SITE: Lot 84 Mills Pond PROPERTY RECORDED: _____
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LSS ~15%	0-6	m-wk SAB BRN CL	1:1 fr					.3+
		6-15	SSAB RC	1:1 fi sl,p.					
		15-48	m-wk SAB RCL	1:1 fr sl,p.					
2	LSS ~15%	0-6	m-wk SAB BRN CL	1:1 fr					.3+
		6-18	SSAB RC	1:1 fi slp-					
		18-36	m-wk SAB RCL	1:1 fr SS,SP.					
			Hit a quartz rock @ 36"						
3	LSS	0-7	m SAB BRN CL	1:1 fr					+3+
		7-32	m SAB R heavy CL	1:1 fi-fr slp-ss,sp.					
		32-48	wk SAB R light CL/heavy L	1:1 fr SS,SP.					
			micaceous, flowing yor						
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____