DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Fredell

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Honeysuckle LLC APPLICATION DATE ___
ADDRESS: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ DATE EVALUATED: ___
LOCATION OF SITE: Honeysuckle Creek Lot 69 PROPERTY SIZE: ___
WATER SUPPLY: ☒ Private ☐ Public ☒ Well ☐ Spring ☐ Other ___ PROPERTY RECORDED: ___
EVALUATION METHOD: ☐ Auger Boring ☒ Pit ☐ Cut
TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	LSS 4-6%	0-12	BSCL CL	fr: SSSP	many 4B mottles 2c drainage 44"+ many manganese stains		—	44"	.2
		12-51	RyBC MFSCL	fr: SP- many					
2		0-23	RC SCL	fr: SP	many Quartz inc.	51"	—	—	.25
		23-51	RCL MFSCL	fr: SSSP- many					
3		0-23	RC ABK	fr: SP SSSP	many SAP	56"	—	—	.3
		23-56	RCL MFSCL	fr: SSSP- many					
4		0-6	BSCL GR	fr: SSSP SSSP					.3 .25
		6-31	RC BRK	fr: SP few YPS SSSP					
		31-56	RCL MFSBK	fr: SSSP SSSP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___

5) 0-5 BSCL WK fr: SSSP
5-22 RC MFSBK fr: SP common YPS .2-.25
22-51 RCL MFSBK fr: SSSP SSSP

6) 0-30 BSCL WEAK fr: SSSP
30-64 RYC MFSBK fr: SP SSSP .25