DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: Franklin

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Homeworks LLC APPLICATION DATE ___
ADDRESS: ___ DATE EVALUATED: ___
PROPOSED FACILITY: ___ PROPOSED DESIGN FLOW (.1949): ___ PROPERTY SIZE: ___
LOCATION OF SITE: Homeworks Trail lot 14 PROPERTY RECORDED: ___
WATER SUPPLY: ☑ Private ☐ Public ☑ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☑ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCY/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Summit CC 8-10%	0-43	BSCL WSMK	fr SSSP Smo					PS .25
		43-66	YRC ARK	fi SP Smo	2 chroma @ 43"+	66	—	43"	(4) @ 43"
2	Top Slope 3% Sl Pond	0-32	YRC Smo	fr SP Smo					(3)
		32-79	YGayC Smo	M vsvp vp	2 chroma @ 29"+	79	—	29"	
3	N	0-6	BSCL fr	fr SSSP Smo					
		6-35	YBRC WSMK	fi SP Smo	many YR5 Chroma 2 @ 46"+				46"
4		0-14	BSCL GR	fr SSSP					PS .25
		14-52	RC ARK	fi SP					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): ___
SITE CLASSIFICATION (.1948): ___
EVALUATED BY: ___
OTHER(S) PRESENT: ___

COMMENTS: ___

2 0-27 BSCL WSMK fr SSP Smo
27-63 RBC ARK/SMK fr SP Smo
.25