DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____


SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: ART
APPLICANT: _____
ADDRESS: _____
APPLICATION DATE: _____
DATE EVALUATED: 4/3/97
PROPOSED FACILITY: _____
PROPOSED DESIGN FLOW (.1949): _____
PROPERTY SIZE: _____
LOCATION OF SITE: Meadowview Lot #5
PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (1941) 1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (1941) 1947 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS 1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS 1943 SOIL DEPTH	OTHER PROFILE FACTORS 1950 SAPRO CLASS	OTHER PROFILE FACTORS 1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	2-4%	0-25	Rd/Vdl Cl m-f SBK	SA VSS SR FR					.3
		25-47	Rd/Vdl Cl m-f SBK						
		Few Vdl. of	SA P, SS, SR FR						
		Few Fine Mag.	concretions						
2		0-24	mbr cl f	f SS/SP					-25
		24-44	sd, ll cl m	f-vf SS/SP					-3
		44-48	Sand bed	Fr to Fri	Mbw 44"				
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____


318'
DRIVE
6'
DRIVE
0.62
60'
17'
32,661 SF
0.75 acres
BASEMENT
CRAWL
60'
4
Drainfield & Repair
50'
22'
333'
DRIVE
DRIVE
15'
19'
34,126 SF
0.78 acres
BASEMENT
CRAWL
60'
5
91'
128'
343'
DRIVE
COS
41,170 SF
0.95 acres
BASEMENT
CRAWL
60'
6
120'
7
91'
372'
DRIVE
57,435 SF
1.32 acres
BASEMENT
CRAWL
8
EX.18" RCP