12751 IREDELL COUNTY HEALTH DEPARTMENT 4645087722

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John Donelson DATE 12/5/91 PERMIT NO. 26-4-B-24

PHONE: Business _____ Home 596-9730

LOCATION Irish Rd, Alcove TR on Templeton, stay L on Templeton, after sharp curve, first house on left. S. R. No. _____

SUBDIVISION NAME RA White Subdivision LOT NO. 24 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )

Character & Porosity of Soil P/clay - sl - fine structure
Percolation Rate .3
Topography 2-4%
Depth to Water Table > 48"
Rock or other impervious formations None Encountered

Lot Area 20,000 FT²

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System IRISH RD.

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 4 @ 100' X 3'
Sq. Ft. 1200 Linear Ft. 400
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Williams Septic Tank

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY AWS

COMMENTS: System shallow - good soil conditions

CERTIFICATE OF COMPLETION BY Wesley Sparks RS. DATE 12/5/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold