98395

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Bobby Saglione DATE 8/31/88 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 21S & I77 TC 1206 TR1108 Rt at Oak Tree on Rt in sharp curve S. R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

See attached note about # Bedrooms 12-15-10

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 3

Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable RS Yes (✓) No. ( )

Character & Porosity of Soil clay
Percolation Rate 60 MPI
Topography Gently
Depth to Water Table 4ft
Rock or other impervious formations none obs.

Lot Area ~3/4Ac

✓ Basement with Plumbing _____ Basement without Plumbing _____ No Basement Upper level



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Gene Jail

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

Basement System
440 gal tank 100 lin ft

IMPROVEMENTS PERMIT BY DLH SR1108

COMMENTS: Well not down.

CERTIFICATE OF COMPLETION BY D. L. Hanson, RS DATE 8-31-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold