184 Iron Gate Circle - Mrsvl. 4645157700

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Rufus Dalton DATE 6-24-74 PERMIT NO. _____

PHONE: Business _____ Home _____


LOCATION Templeton Rd 1108 left on 1181. ¼ mi Turn left ¼ down this Rd S. R. No. 1181

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3
Garbage Disposal Unit Yes (✓) No ( )
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site Suitable Yes (✓) No ( )
Lot Area ¾ acre

Character & Porosity of Soil Clayloam (Porosity Fair to Poor)
Percolation Rate 50 min/inch
Topography 3% Slope
Depth to Water Table 8 to 10' to Lake Level
Rock or other impervious formations none



Plot of System

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 945 Linear Ft. 315
Depth of Stone in Lines 10"
Water Supply: Individual (✓)
Public ( )

Installed by F. J. Ervin

IMPROVEMENTS PERMIT BY J. C. Moore

COMMENTS: House or well not located at this time. House to be located below septic tank lines and no foundation shall be closer than 10' to tank or lines. Well should be 100' from tank or lines

CERTIFICATE OF COMPLETION BY J. C. Moore DATE 6-24-74

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold