4645-16-7467

12825

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Vida Mae Gray DATE Nov. 25, '91 PERMIT NO. 2H-11-C-127

PHONE: Business _____ Home _____

LOCATION 215 x I77 TR 1126 (Alcove) TR 1108 (Templeton) Bear left on Camino Real R Queens Circle TR Forum Dr. attend on R S. R. No. _____

SUBDIVISION NAME Queens Cove LOT NO. 127 SECTION OR BLOCK NO. 3

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 3

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ Yes ( ) No ( )

Lot Area 1.5 Ac

Character & Porosity of Soil ps clay


Percolation Rate 1 in 3

Topography 2-4%

Depth to Water Table 4'+

Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1500 Gals.

Nitrification Field:

No. of Lines 4+4 w/ 1 Flow Diverter

Sq. Ft. 1620 Linear Ft. 540

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by Mikey Bean

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Forum Drive

CERTIFICATE OF COMPLETION BY DR Hinson, RS. DATE 11-25-91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold