DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: George Moore APPLICATION DATE _____
ADDRESS: 142 Circle View Dr. DATE EVALUATED: _____
PROPOSED FACILITY: 3 BD. PROPOSED DESIGN FLOW (.1949): 360 PROPERTY SIZE: 1.0 AC
LOCATION OF SITE: Hacklebarney Rd. TR Circle View Dr., #142 PROPERTY RECORDED: _____
WATER SUPPLY: [X] Private [ ] Public [ ] Well [ ] Spring [ ] Other _____
EVALUATION METHOD: [X] Auger Boring [ ] Pit [ ] Cut
TYPE OF WASTEWATER: [X] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Rear 1-2%	0-10	GR - sl	VFR. NS-WP	B				
		11-28	wk SBK SEXP cl	FR. SS-SP	R				
		29-40	SBK - cl SEXP SAP	Fi SS-SP	M - 7R				
		41-49	MGR - SCSAP NEXP	Fr SS-SP	M - 7R				
2	Front hole CC	0-6	SBK - cl	FR S-P	B				
		7-16	wk M cSAP	FR S-P EXP	M B-R				
		17-23	wk M C	Fi VEXP S-P	W CM2-BR				
		24	M EXP						u
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		PS
System Type(s)		14" PPBPS
Site LTAR		.3

OTHER FACTORS (.1946): Well, Road R/W
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Mark
OTHER(S) PRESENT: George Moore, Joe Moore

COMMENTS: _____