TIPPAH COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Larry W. Kistler

ADDRESS:

COUNTY: Tippah

DATE REQUESTED: 9-2-80

PLAT NO.:

LOT SIZE: 160 x 290

LOCATION OF SITE: 215 X-T-77 TR 1206 about ½ mile TR Waters Edge Drive 4th lot on R

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-4% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) Subangular U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48+ U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS None observed U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S (PS) None observed U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS ~100 mpi U	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	PS			
SOIL SERIES				

S - Suitable PS - Provisionally Suitable U - Unsuitable

See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Keep System Shallow

Described By: Fred Clemmer

Title: S-T

Date: 9-2-80

Form 2601 (2/77)
Substitution