VISION OF ENVIRONMENTAL HEALTH

PROPERTY ID #:

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

DDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 8-23-01

OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____

OCATION OF SITE: Lot 53 Tanglebriar Farms PROPERTY RECORDED: _____

ATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____

ALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut

PE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
(1)	0-40	M-fr ar RC	fr sp fr vr sl sp					I-25
(2)	0-4	wk sbk br sl	sl fi (dry) ss sp					I-25-3
	4-20	sbk RC	fi sp ss sp					
	20-41	wk sbk gr cl	fr sl sp ss sp mpo sp					

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
ilable Space (.1945)		
Type(s)		

OTHER FACTORS (.1946): _____

SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____