4645 75 3254

IREDELL COUNTY HEALTH DEPARTMENT

14364

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR James R. Kaufman DATE Nov. 24, '92 PERMIT NO. 24 B75

PHONE: Business _____ Home _____

LOCATION 115 S. TR 1102 (Sanctree) just before I77 TR at Community Baptist Church (2nd entrance) behind graveyard 1000' on right S.R. No. _____

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other _____

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ☐ No ☑

Auto. Dishwasher Yes ☑ No ☐

Auto. Wash. Machine Yes ☑ No ☐

Lot Area 9 Acres

Soil Characteristics PsClay


Application Rate .35

Topography 4%

Depth to Water Table 74'

Rock or other impervious formations None obs.

_____ Basement with Plumbing Repair Area _____ Basement without Plumbing ✓ No Basement ✓ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. 1035 Linear Ft. 345 +

Depth of Stone in Lines 12"

Water Supply: Individual ☑ Public ☐

Installed by AJ Erwin

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: _____

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY _____

COMMENTS well not installed as of 11/24/92

CERTIFICATE OF COMPLETION BY DR Hmm, RS DATE 11/24/92

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

14364

IREDELL COUNTY HEALTH DEPARTMENT

IMPROVEMENT PERMIT AND CERTIFICATE OF COMPLETION / OPERATIONS PERMIT

OWNER OR CONTRACTOR James R Kaufman DATE Oct 21, '92 PERMIT NO. 24875

PHONE: Business _____ Home _____


LOCATION 1655 TR SR 1102 (Langtree) just before I-77
TR at Community Bapt. Church 2nd paved entrance behind graveyard S.R. No. 1000' on RT

SUBDIVISION NAME _____ LOT NO. _____ SECTION OR BLOCK NO. _____

House ☑ Mobile Home ☐ Business ☐ Other Redrawn I.P.

No. Bedrooms 3 No. Bathrooms 2 Soil Characteristics fsclay/clay loam
Garbage Disposal Unit Yes ☐ No ☑ Application Rate .35
Auto. Dishwasher Yes ☑ No ☐ Topography 4%
Auto. Wash. Machine Yes ☑ No ☐ Depth to Water Table 41
Lot Area 1 Acres Rock or other impervious formations NONE OBS

Basement with Plumbing Repair Area Basement without Plumbing ☑ No Basement ☑ Crawl Space



Plot of System (Not to Scale)

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 1035 Linear Ft. 345
Depth of Stone in Lines 12"
Water Supply: Individual ☑ Public ☐

Installed by _____

I understand and agree to install a septic tank system as specified on this Improvement Permit.

Signed: X James Kaufman

(IMPROVEMENT PERMIT IS VALID FOR 60 MONTHS FROM DATE OF ISSUE.)

IMPROVEMENT PERMIT BY Driveway DR Hanson, RS.

COMMENTS Follow contour.
36" max Trench bottom depth.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS

Permit is VOID if any unauthorized changes are made in installation of system, and/or if any unapproved changes are made to the site, and/or if any false information is supplied toward securing Improvement Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

4 Acres Private Lot to SR1102