DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

SHEET 1 OF 1
PROPERTY I.D.#: 2K34 50
PROPERTY RECORDED: YES
COUNTY: Iredell

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Robert Brolin OWNER: AGENT: ✓ PHONE:
ADDRESS: APPLICATION DATE: DATE EVALUATED: 8/3/93
PROPOSED FACILITY: 3 bedroom SF Dwelling
PROPERTY SIZE:
LOCATION OF SITE: lot 50 Crystal Bay
WATER SUPPLY: On-Site Well ✓ Comm. Well Public Other EVAL. METHOD: Auger Boring Pit ✓ Cut

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1		0-20"	sbk c	1:1 / fr	—	—	PS	—	.3-.35
		20-48"	wk sbk scl	1:1 / fr	—	—	PS	—	.25-.3
2									
3									
4									
5									

AVAILABLE SPACE (.1945) PS SITE CLASSIFICATION (.1948): PS SITE LONG-TERM ACCEPTANCE RATE: .3 at 18"-20"
EVALUATED BY: DP Hinson OTHER(S) PRESENT: Bob MacLeod, Robert Brolin
COMMENTS: lot recorded in 1965, repair area is for 100% PPBPS