11053

IREDELL COUNTY HEALTH DEPARTMENT

4646-04-5276

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Steve Lang DATE 7/17/90 PERMIT NO. 26-19-A-72

PHONE: Business _____ Home _____

LOCATION 1100 TL 1179 (Canvasback) TL Broadbill at end

S. R. No. _____

SUBDIVISION NAME Woodland Hills LOT NO. 72 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 3½

Garbage Disposal Unit	Yes (✓)	No ( )	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Ps clay

Percolation Rate No. 3

Topography near street 4-6% D

Depth to Water Table 3½

Rock or other impervious formations 3½+

Lot Area 20000 Ft² very limited useable space Existing lot

(✓) Basement with Plumbing ( ) Basement without Plumbing ( ) No Basement

Dellinger Tanks 1000 PT

Size of Tank 1500 Gals.

Nitrification Field:

No. of Lines 3

Sq. Ft. _____ Linear Ft. 200

Depth of Stone in Lines 1'+

Water Supply: Individual ( ) 16"


Public (✓) Panel

C.W.

Installed by Bob Macleod

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed _____



Plot of System

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

Operation Permit

CERTIFICATE OF COMPLETION BY Sam Ingram EHS DATE 7/17/90

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold