4646-04-5870

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR C. W. BREWER DATE 2/5/88 PERMIT NO.

PHONE: Business 663-4669 Home

LOCATION 1100 TL CANVASBACK (1179) TL 2nd Woodduck Lp. TR 1264 CRYSTAL CIRCLE TR 1st Road Lot on L. past TOPAZ PL. S. R. No.

SUBDIVISION NAME CRYSTAL BAY LOT NO. 46 SECTION OR BLOCK NO.

House (✓) Mobile Home ( ) Business ( ) Other


No. Bedrooms 3 No. Bathrooms 2 1/2

Garbage Disposal Unit	Yes ( )	No (✓)	
Auto. Dishwasher	Yes (✓)	No ( )	
Auto. Wash. Machine	Yes (✓)	No ( )	
Site Suitable	Yes (✓)	No ( )	

Character & Porosity of Soil Clayey
Percolation Rate ~ .4 gpd/ft²
Topography 4 - 6%
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area ~ 1/2 ACRE

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Plot of System NTS.

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by WAYNE ORBISON

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY A.C.P., S.T.

COMMENTS:

CERTIFICATE OF COMPLETION BY Andie C. Pierce DATE 2/5/88

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold