4646046121

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR LEE & BETTY IVESTOR DATE 9/11/87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 T.L. 1179 (Canvasback) T.L. Broadbill at end of Cul de Sac. S. R. No. _____

SUBDIVISION NAME WOODLAND HILLS LOT NO. 73 SECTION OR BLOCK NO. 5

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Character & Porosity of Soil Clayey
Percolation Rate 4 gpd / ft²
Topography 6-8%
Depth to Water Table 4'+
Rock or other impervious formations none observed

Lot Area .6 ACRE

✓ Basement with Plumbing _____ Basement without Plumbing _____ No Basement



Plot of System N.T.S.

1000 gal pump tank w/o baffle

Size of Tank 1500 Gals.

Nitrification Field:
No. of Lines 3
Sq. Ft. _____ Linear Ft. 150' of
Depth of Stone in Lines T&J Panel

Water Supply: Individual ( )
Public (✓)
COMMUNITY well

Installed by F.J. ERVIN

I understand and agree to install septic tank system as specified on this Improvement Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: PRESSURE DOSED. Ckd alarm (high water) ACP/DR
-10/28/87

CERTIFICATE OF COMPLETION BY Andrea C. Brown DATE 10/28/

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold