4310

IREDELL COUNTY HEALTH DEPARTMENT

4616-07-0395

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER/CONTRACTOR G & O Contractors DATE 9/20/89 PERMIT NO. 2K-11-A-19

PHONE Business _____ Home 664-6060

LOCATION 1100 TL 1179 (Canvasback) TL 1st Wood Duck loop ~ 1/8 mile on Rt.

SUBDIVISION NAME Lakeside Farms LOT NO. 19 SECTION OR BLOCK NO. _____ S. R. No. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2 1/2

Garbage Disposal Unit	Yes (✓)	No ( )
Auto. Dishwasher	Yes (✓)	No ( )
Auto. Wash Machine	Yes (✓)	No ( )
Site Suitable	Yes (✓)	No ( )

Lot Area ~20,000 ft²

Character & Porosity of Soil Clay
Percolation Rate ~.3-.35 gpd/ft²
Topography 6-10%
Depth to Water Table 4'+
Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System Not to Scale

Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 6
Sq. Ft. 1500 Linear Ft. 350'+
Depth of Stone in Lines 12"
Water Supply: Individual (~~✓~~)
Public (~~✓~~)

Installed by F. J. Ferrell

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH, R.S.

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Pierce, R.S. DATE 9/20/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold