4646-07-2288

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Sherrill Law Construction DATE _____ PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1100 TR 1179 (Canvasback) TR 1st Wood Duck Loop
~1/4 mile on Rt. S. R. No. _____

SUBDIVISION NAME Lakeside Farms LOT NO. 17 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay	
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	~.35	
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	4-10%	
Site Suitable in back	Yes (✓)	No ( )	Depth to Water Table	4'+	
			Rock or other impervious formations	none obs.	

Lot Area 90'X180'

1000 gal pumptank

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement



Plot of System

Size of Tank 1000 Gals.

Nitrification Field:
No. of Lines 5
Sq. Ft. 1050 Linear Ft. 350
Depth of Stone in Lines 12"

Water Supply: Individual ( )
Public (✓)
Community Well

Installed by Sterling Church

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY DRH

COMMENTS: Drainfield installed and tanks set and approved on 9-15-87. Pump, pumpline, floats and alarm not yet installed. 3/4 H.P. pump installed, pumpline & alarm checked 2-1-88 (Access Riser on pump tank yet to be installed) DRH.

CERTIFICATE OF COMPLETION BY Andrie C. Pierce DATE 2-3-88

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold