DEPARTMENT OF ENVIRONMENT,
HEALTH, & NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH


SHEET ____ OF ____
PROPERTY I.D.#: ____
PROPERTY RECORDED: ____
COUNTY: ____

SOIL/SITE EVALUATION
FOR
ON-SITE WASTEWATER SYSTEM

APPLICANT: Bill Woodard OWNER: AGENT: PHONE: ____
ADDRESS: ____ APPLICATION DATE: ____ DATE EVALUATED: 1-27-95
PROPOSED FACILITY: 2 bedroom SFR / ~~duplex~~
PROPERTY SIZE: ____
LOCATION OF SITE: lot 1 Timber Hill Village
WATER SUPPLY: On-Site Well ____ Comm. Well ____ Public ____ Other ____ EVAL. METHOD: Auger Boring ✓ Pit ____ Cut ____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	middle to front	0-17	SaLo - CL						
		17-36	wwet Sap						
		36-45	wk SAbk - CL - Sappy						
2	Back of lot	0-24	wk SAbk - CL			24"+			
		24"	Hitrock						
			numerous outcrops in backyard						
3	left front	0-12	SaLo - CL						.3
		12-24	SaLo - C						
		24-48	wk SAbk CL						
4	middle to left of #1 ~10' down hill	0-20	C SaLo						
		20-40	CL wk SAbk						
		40-44+	Sap						
5									

AVAILABLE SPACE (.1945): ____ SITE CLASSIFICATION (.1948): ____ SITE LONG-TERM ACCEPTANCE RATE: .3-.35
EVALUATED BY: DEH OTHER(S) PRESENT: ____
COMMENTS: Shallow conv system on left front portion of lot
Repair area not applicable - Not recorded in date 60's - early 70's


35'
Hs
contour
250' Drainfield area
~60'
10'
Street R/W