DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Robert Gregory
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: Residential PROPOSED DESIGN FLOW (.1949): 480 gpd DATE EVALUATED: 12-22-05
LOCATION OF SITE: _____ PROPERTY SIZE: _____
PROPERTY RECORDED: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	linear FP 4%	0-28	lsbkc						.25
		28-48	c+s/sapl & ss/sp se						
			w/high mica content						
2		0-24	lsbkc	fr ss/sp se					.3
		24-48	lsbkcl/l						
			high mica content						
3		0-20	lsbkc	fr ss/sp se					.3
		20-21	gravel layer <50%		dark stones				
		21-48	lsbkcl		may be very old septic line				
4		0-28	lsbkc	fr ss/sp se					.25
		28-29	scl	may be relic	10YR 6/2				
		29-48	lsbkcl						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	yes	at least partial
System Type(s)	panel	panel
Site LTAR	.3	.25

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Judy Melville
OTHER(S) PRESENT: _____

COMMENTS: _____