IREDELL COUNTY HEALTH DEPARTMENT

APPENDIX H

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Phil Lipe

ADDRESS:

COUNTY: Iredell

DATE REQUESTED:

PLAT NO.:

LOT SIZE: 100 X 200

LOCATION OF SITE: Catalina Cove Lot 17

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 4-6% Depressional	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U — clayey	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U — SAB	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S (PS) U — 46"+	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U — 280	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
SITE CLASSIFICATION*	P.S.			
SOIL SERIES				

S - Suitable PS - Provisionally Suitable U - Unsuitable

See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Keep system shallow

Described By:

Title: S

Date:

Form 2601 (2/77)
Limitation