WASTEWATER SECTION COUNTY

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

R: Bobby Gaddy APPLICANT: _____
SS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3/3/97
SED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
TION OF SITE: 195 Coastal Breeze PROPERTY RECORDED: _____
R SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
ATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut
F WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed
Repair

55' Pool 60' Lines

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-9"	Sdy Cl		Pd Brn				.3
		9"-23"	SCK RC						
		23"-48"	Y-R SaCl		Few F-Brn Mott				
2									
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Trench Space (.1945)		
Trench Type(s)		
LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____