DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Kidd
ADDRESS: _____ APPLICATION DATE _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 10-9-12
LOCATION OF SITE: Lakeside Cove Lot #1 PROPERTY SIZE: _____
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Alt-1	0-10	Rd/Brn SCL	GR FR					PS .325
		10-40"	R C m-w SBK SS, SP, SE FR						
		40-48"	R CL w SBK SS, SP, SE FR						
			w/ Some SAP Inclus.			48"			
2	Alt-2	0-10	Rd/Brn SCL						PS .325-.3
		10-40	R C m-w SBK SS, SP, SE FR						
			w/ Some SAP Inclus.			48"			
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	II
Site LTAR	.325	.3

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: M. Dotson
OTHER(S) PRESENT: Mike Kidd

COMMENTS: _____

DEPARTMENT OF ENVIRONMENT, HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: ___
COUNTY: ___

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: Mike Kidd
ADDRESS: ___
APPLICANT: ___
APPLICATION DATE: ___
PROPOSED FACILITY: ___
PROPOSED DESIGN FLOW (.1949): ___
DATE EVALUATED: 9/14/10
LOCATION OF SITE: Hillside Cove Lot #4
PROPERTY SIZE: ___
PROPERTY RECORDED: ___
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other ___
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

SE = Slightly Exp

PROFILE #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Pit LL 5-6%	0-8	Brw SCL						PS .3-.325
		8-21	Rd C MSBK						
		21-47"	Rd C/C w/SBK SS,SP SE,FR			47"+			
2	Pit LL 5-6%	0-10	Brw SCL						PS .3+
		10-19	Rd C mSBK						
		19-46"	Rd C/C w/SBK SS,SP SE,FR			46"+			
3	LL 5-6%	0-12	Brw SCL						PS .3+
		12-42	Rd C/C w/SBK SS,SP SE,FR			42"+			
4	Pit 10-9-12	0-10	Rd Brw SCL						PS .325
		10-40	RC m-w	SBK SS,SP SExp, FR					
		40-48"	RC/ w SBK SS,SP SExp, FR						
			w/ some SAP Indic						
		AH-2	same as AH-1						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	PS	PS
System Type(s)	III	II
Site LTAR	.3+	.3+

OTHER FACTORS (.1946): None
SITE CLASSIFICATION (.1948): PS
EVALUATED BY: Maria Dotson
OTHER(S) PRESENT: Mike Kidd