4646-22-8976

09282

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION 2H-1-A-37

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Robert Cadieu DATE Mar 6, 1990 PERMIT NO. 21 A

PHONE: Business _____ Home _____

LOCATION 1109 TR 1191 (Ponderosa) Bear left at forks ~1/4 mi on left S. R. No. _____

SUBDIVISION NAME Bonanza LOT NO. 37 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 4 No. Bathrooms 3½

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	~3
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	~4%
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	4'+
			Rock or other impervious formations	none obs.

Lot Area _____

(✓) Basement with Plumbing ____ Basement without Plumbing ____ No Basement

1250 A T

Size of Tank 1250 S T Gals.


Nitrification Field: Conventional Trench

No. of Lines 8

Sq. Ft. 1641 Linear Ft. 547'

Depth of Stone in Lines _____

Water Supply: Individual (✓)
Public ( )



Ponderosa Circle Plot of System

Installed by Walter Barton

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Sam Ingram EH-S DATE Mar 6, 1990

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold