4646-22-9974

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR William Burnette DATE July 30, '87 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 1109 TR 1191 (Ponderosa) Bear left at forks ~ 1/4 mi. on left S. R. No. _____

SUBDIVISION NAME BONANZA LOT NO. 38 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____


No. Bedrooms 3 No. Bathrooms 2-3

Garbage Disposal Unit	Yes	(✓)	No	( )
Auto. Dishwasher	Yes	(✓)	No	( )
Auto. Wash. Machine	Yes	(✓)	No	( )
Site Suitable	Yes	(✓)	No	( )

Character & Porosity of Soil Shallow clay
Percolation Rate .4 gpd/ft²
Topography 8-10%
Depth to Water Table 3'+
Rock or other impervious formations none observed

Lot Area Existing ~ 20000ft²

✓ Basement with Plumbing ____ Basement without Plumbing ____ No Basement Pump 1000 gal.



Size of Tank 1250 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. ~~___~~ Linear Ft. 150
Depth of Stone in Lines 16" T&J panels
Water Supply: Individual (✓)
Public ( )

Installed by Ray Beam

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY David R. Hinson

COMMENTS: lines and tanks ckd @ July 30, 1987. Ck. Pump and alarm & well.
Alarm Checked 10/29/07

CERTIFICATE OF COMPLETION BY Andre C. Brown DATE 10/29/07

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold