06885

(77)4646-23-5367

IREDELL COUNTY HEALTH DEPARTMENT (78)4646-23-6353

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Louis Picard DATE Feb 15, 88 PERMIT NO.

PHONE: Business Home

LOCATION 1109 SR 1191 (Penhouse Circle) Bear left at forks ¼ mile on Rt S. R. No.

SUBDIVISION NAME Bonanza LOT NO. 27478 SECTION OR BLOCK NO.


House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)
Auto. Dishwasher Yes (✓) No ( )
Auto. Wash. Machine Yes (✓) No ( )
Site ~~Suitable~~ P.S. Yes (✓) No ( )
Lot Area 20000+

Character & Porosity of Soil Clay
Percolation Rate 3-4 mpi
Topography Sl
Depth to Water Table 4'+
Rock or other impervious formations none obs.

___ Basement with Plumbing ___ Basement without Plumbing ✓ No Basement



Plot of System

Street

Size of Tank 1000 Gals.
Nitrification Field:
No. of Lines 3
Sq. Ft. 900 Linear Ft. 300
Depth of Stone in Lines 12"
Water Supply: Individual (✓)
Public ( )

Installed by Hunt Woodleaf

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed:

IMPROVEMENTS PERMIT BY DRH

COMMENTS:

CERTIFICATE OF COMPLETION BY DRH Hinson, RS DATE Feb 15, 88

EXISTING SYSTEM CHECKED BY: DATE

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold