ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: lot 63 Sunlown PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-6	GSL vfr	fri SSSP					PS
		6-36	RL ABK	fri SP - few YBs					.25
		36-60	RL MBK	fri SSSP - few YBs					
2		0-4	RSL WSBK	fr. SS SP					PS
		4-24	RL MBK/SBK	fri S, P - few YBs					.25
		24-54	YRL WSBK	fr. SS SP					.3
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____

EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

DRIVE

65
25,000.00 sq.ft.

60x70

100.00'

250.00'

DRIVE

64
25,000.00 sq.ft.

60x70

100.00'

250.00'

DRIVE

63
25,000.00 sq.ft.

60x70

100.00'

250.00'

DRIVE

62
25,000.00 sq.ft.

60x70

825

100.00'

250.00'

DRIVE

61
25,000.00 sq.ft.

60x70

100.00'

250.00'

DRIVE

CORONA CIRCLE

S87° 58'58"E
695.32'

4' SIDEWALK

2' VALLEY GUTTER

50'

24'

0.96'

83.96'