...ARTMENT OF ENVIRONMENT AND NATURAL RESOURCES
...SION OF ENVIRONMENTAL HEALTH
...ITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM


...WNER: _____ APPLICATION DATE _____
...DDRESS: _____ DATE EVALUATED: _____
...OPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
...OCATION OF SITE: Lot 80 Sunlan Cove PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
...VALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
...YPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-4	BSiL GR	fr SSSP					PS -3
		4-24	BL ANH	fr SP					
		24-48	KL MSHR	fr SSSP					
2		0-12	BSiL GR	fr SSSP					PS -3
		12-47	BL MSHR	fr SP					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____


84
25,600.00 sq.ft.
83
25,600.00 sq.ft.
82
25,600.00 sq.ft.
81
25,600.00 sq.ft.
80
25,600.00 sq.ft.
79
SUNDOWN COVE DRIVE
DRIVE
256.00'
100.00'
101.64'
99.94'
194.53'
50' R/W
22' EOP
9+00
8+00
7+00
6+00
5+00
4+00
WRONG LOT - 80x80
60x70
830
840