ON-SITE WASTEWATER SECTION

PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION
for ON-SITE WASTEWATER SYSTEM

OWNER: _____ APPLICATION DATE _____
ADDRESS: _____ DATE EVALUATED: _____
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 61 Sunlawn PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1		0-12	BSCL GR	fr: SSSP					PS .3
		12-52	R C/CL MPSBK	fr: SSSP					
2		0-11	BSCL WSBK	fr: SSSP					PS .25 .3
		11-28	R CL MPABK	fr: SSSP + few YBS					
		28-52	YBCL WSBK	fr: SSSP + Fr - SAP					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)		
System Type(s)		
Site LTAR		

OTHER FACTORS (.1946): _____
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: _____
OTHER(S) PRESENT: _____

COMMENTS: _____

CORONA CIRCLE

61
25,000.00 sq.ft.
60x70

62
25,000.00 sq.ft.
60x70

63
25,000.00 sq.ft.
60x70

64
25,000.00 sq.ft.
60x70

65
25,000.00 sq.ft.
60x70

DRIVE

250.00'

100.00'

S87° 58'58"
695.32'

2' VALLEY GUTTER

4' SIDEWALK

83.96'

96.0'