IREDELL COUNTY HEALTH DEPARTMENT 4644-29-1440

12491 (SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tom Kirkland DATE 8/30/91 PERMIT NO. 2K-22-A-16

PHONE: Business 664-7000 Home

LOCATION Farmstead Estates PH II, Brawley School TL into Farmstead straight to back cul de sac, house on R S. R. No. 1100

SUBDIVISION NAME Farmstead Estates LOT NO. 52 SECTION OR BLOCK NO. II

House (✓) Mobile Home ( ) Business ( ) Other

No. Bedrooms 4 No. Bathrooms 2

Garbage Disposal Unit Yes ( ) No (✓)

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Character & Porosity of Soil clay-f-ss-p

Percolation Rate 35'


Topography 2-4%

Depth to Water Table >40"

Rock or other impervious formations None observed

Lot Area 20000 FT²

____ Basement with Plumbing ____ Basement without Plumbing ✓ No Basement



Plot of System CUL DE SAC

Size of Tank 1000 Gals.

Nitrification Field:

No. of Lines 40 100

Sq. Ft. 1200 Linear Ft. 400

Depth of Stone in Lines 12"

Water Supply: Individual (✓)

Public ( )

Installed by EJ Erwin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Wesley Sparks RS DATE 8/30/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold