4646305686

91-7

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tillman Rogers DATE 5/18/89 PERMIT NO. 21A

PHONE: Business _____ Home 663-0026 day: 663-3821

LOCATION 21 S. TL Alcove TR Catalina On L. near end. Just b/f House on left S. R. No. _____

SUBDIVISION NAME Catalina Cove LOT NO. 12 SECTION OR BLOCK NO. _____

Tax: 8G-5-C-12

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms _____

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site Suitable Yes (✓) No ( )

Lot Area ~ 1/2 ACRE –

Character & Porosity of Soil Clayey (Silty)


Percolation Rate .35 gpd/ft²

Topography 6%

Depth to Water Table 4'+

Rock or other impervious formations none observed

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 4
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by F. J. Ervin

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Andrew C. Pierce

COMMENTS: _____

CERTIFICATE OF COMPLETION BY Andrew C. Pierce DATE 5/18/89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold

09/19 - PROPERTY DESCRIPTION

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Tillman Rogers DATE 10/11/88 PERMIT NO. 21 A

PHONE: Business _____ Home 663-0026 dy 663-3821

LOCATION 21 S T & L Alcove TR Catalina On L. near end. Just b/f last Hse on Left. S. R. No. _____

SUBDIVISION NAME CATALINA COVE LOT NO. 12 SECTION OR BLOCK NO. _____

TAX: 2G-5-C-12


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 2 No. Bathrooms _____

Garbage Disposal Unit	Yes (✓)	No ( )	Character & Porosity of Soil	Clayey (silty)
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.35 gpd/ft²
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	Hilo
Site Suitable	Yes (✓)	No ( )	Depth to Water Table	41+
			Rock or other impervious formations	none observed

Lot Area ~ 1/2 ACRE - NOT SHOWN ON P.D.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System NOT TO SCALE

Size of Tank 1250 Gals.

Nitrification Field:
No. of Lines 3-4
Sq. Ft. 720 Linear Ft. 240
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY Andre C. Price

COMMENTS: Keep DRAINFIELD SHALLOW AND ON CONTOUR. NO DEEPER THAN 30". KEEP THE 5' SEPARATION FROM DWELLING AND ANY PROPOSED DECK/ PORCH ADDITIONS.

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold