4646-33-4680

11114

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John W. Coble DATE 2/8/91 PERMIT NO. 2H-1-A-58

PHONE: Business _____ Home 663-1472

LOCATION 1109, TL PONDEROSO, 2ND HOUSE ON (L) AFTER GRAVEL ROAD

_____ S. R. No. _____

SUBDIVISION NAME BONANZA LOT NO. 58 SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit	Yes	(✓)	No	( )	Character & Porosity of Soil: CLAYEY
Auto. Dishwasher	Yes	(✓)	No	( )	Percolation Rate: .3
Auto. Wash. Machine	Yes	(✓)	No	( )	Topography: 5-10%
Site Suitable	Yes	(✓)	No	( )	Depth to Water Table: >3'
					Rock or other impervious formations: NONE OBSERVED

Lot Area 20,000 FT²

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1500 / 1500 Gals.

Nitrification Field: 3/18/91 HWS

No. of Lines 4 ✓ @ 50' Sq. Ft. _____ Linear Ft. 200'

Depth of Stone in Lines _____

Water Supply: Individual (✓) 16" T+J PANEL SYSTEM 46 PANELS

Public ( )

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY _____

COMMENTS: Repair Area in Rear 50' away from the Drilled Well location. 2/8/91 Completed SIT, PIT, Supply Line, Drainlines, adjusted pressure on each laterals. 3/18/91 Pump, alarm, high water float installed properly

CERTIFICATE OF COMPLETION BY (OPERATIONS) Wesley Sparks DATE 3/18/91

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold