40

11114

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION

(Ground Absorption Sewage Disposal System – G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR John W. Coble DATE Mar 28, 1990 PERMIT NO. 2H-1-A-58

PHONE: Business _____ Home 663-1472

LOCATION 11 09 TL Ponderosa 2nd House on left after gravel road to left S. R. No. _____

SUBDIVISION NAME Bonanza LOT NO. 58 SECTION OR BLOCK NO. _____

House (✓) Mobile Home ( ) Business ( ) Other _____

No. Bedrooms 3 No. Bathrooms 2½

Garbage Disposal Unit Yes (✓) No ( )

Auto. Dishwasher Yes (✓) No ( )

Auto. Wash. Machine Yes (✓) No ( )

Site ~~Suitable~~ PS Yes (✓) No ( )

Lot Area 20,000 ft²

Character & Porosity of Soil clayey


Percolation Rate ~.3 gpd/ft²

Topography 5% 10%

Depth to Water Table 3'+

Rock or other impervious formations none obs.

_____ Basement with Plumbing ✓ Basement without Plumbing _____ No Basement



Plot of System

Size of Tank 1250 Gals.

Nitrification Field:

No. of Lines 5@40'

Sq. Ft. _____ Linear Ft. 200'

Depth of Stone in Lines 12"

Water Supply: Individual (✓) 16"

Public ( ) T+T

46 Panels Panel

Installed by _____

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: John W. Coble

IMPROVEMENTS PERMIT BY Sam Ingram EH&S

COMMENTS: Front of house must set 114' from front property line

Use 2 D-Boxes with 4:2 Reducers and Speed Levelers

20 gpm 15' TDH

Change to pump 8/22/90

CERTIFICATE OF COMPLETION BY _____ DATE _____

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold