SOIL/SITE EVALUATION

(Continuation Sheet)

Sheet ____ of ____

DEPARTMENT OF ENVIRONMENT
AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH

Marvin Brotherton
Ponderosa

PROPERTY ID #: ____
DATE OF EVALUATION: 9/30/02
COUNTY: Transylvania

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	OTHER PROFILE FACTORS .1943 SOIL DEPTH	OTHER PROFILE FACTORS .1956 SAPRO CLASS	OTHER PROFILE FACTORS .1944 RESTR HORIZ	PROFILE CLASS & LTAR
		0-18"	Brw C	m SBK S, P, SE F-FR					PS
		18"-36"	Yel/Brw CL w/	SBK SS, SP SE FF-FR					.25
			w/ Brw to mar	y SAP Indus					
		36"-48"	Yel/Brw L/SL	SAP w/ Cl Indus					
	Repair	0-26"	Rd/Brw C/CL	m SBK SS, SP, SE, FR-F					PS
		26"-40"	Rd/Brw to Yel/Brw	CL w/ SBK					
			SS, SP SE	w/ Few to mar SAP Indus					.25 to
		40-48"	Yel/Brw	L/SL SAP					.3
		0-24"	Brw CL	m w SBK SS, SP SE FR					PS
		24-48"	Dull Brw CL	w SBK SS, SP SE					
				FR					
			w/ Some Yel/Brw	mottles					.25

COMMENTS: ____