DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

Sheet ___ of ___
PROPERTY ID #: _____
COUNTY: _____

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: George Church
ADDRESS: _____ APPLICATION DATE 12/01/03
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ DATE EVALUATED: 12/19/03
LOCATION OF SITE: Lot 52 MORGANA EST. ZEPHYR DR. PROPERTY SIZE: .46 AC
WATER SUPPLY: ☑ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____ PROPERTY RECORDED: _____
EVALUATION METHOD: ☑ Auger Boring ☐ Pit ☐ Cut
TYPE OF WASTEWATER: ☑ Sewage ☐ Industrial Process ☐ Mixed

PROFILE #	.1940 LAND-SCAPE POSITION/ SLOPE %	HORI-ZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941) .1941 STRUCTURE/ TEXTURE	SOIL MORPHOLOGY (.1941) .1941 CONSISTENCE/ MINERALOGY	OTHER PROFILE FACTORS .1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	PROFILE CLASS & LTAR
1	Front 2%→3 F→B CC (L)	0-6	sbk / sl	VFR - NS - NP	BR/BR				
		7-27	sbk wk / sc	FI - SS - SP					
		28-41	wk / c	FI SS-SP (R)	few CH3 mot.				
		42-49	GR / sc	FR SS-SP (R)	CH3 (R)				
2	Front 2% NCC (L)	0-13	BR / l	VFR - S - SP	BR/BR				
		14-31	sbk / scl	FR - SS - SP	few CH3 mot. R				
		32-49	GR / scl	VFR SS - SP					
3									
4									

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM
Available Space (.1945)	" u "	< 93'
System Type(s)	16" PPRPS	
Site LTAR	.3	

OTHER FACTORS (.1946): Well on (R)
SITE CLASSIFICATION (.1948): _____
EVALUATED BY: Spinks
OTHER(S) PRESENT: D. Church.

COMMENTS: _____