4646367336

IREDELL COUNTY HEALTH DEPARTMENT

(SEPTIC TANK) IMPROVEMENTS PERMIT AND CERTIFICATE OF COMPLETION
(Ground Absorption Sewage Disposal System -- G. S. Chapter 130-Article 13C)

OWNER OR CONTRACTOR Ronald W. Scott DATE April 14, '89 PERMIT NO. _____

PHONE: Business _____ Home _____

LOCATION 150 W. SR 1109 TR 1190 (Sandown Rd.) TL Elysian Drive TL Zephyr Lane ~250' on right S. R. No. _____

SUBDIVISION NAME Moorland Estates LOT NO. ? SECTION OR BLOCK NO. _____


House (✓) Mobile Home ( ) Business ( ) Other Repair

No. Bedrooms 3 No. Bathrooms 2

Garbage Disposal Unit	Yes ( )	No (✓)	Character & Porosity of Soil	clay
Auto. Dishwasher	Yes (✓)	No ( )	Percolation Rate	.3-.4
Auto. Wash. Machine	Yes (✓)	No ( )	Topography	2%
Site ~~Suitable~~ RS	Yes (✓)	No ( )	Depth to Water Table	6'+
			Rock or other impervious formations	none obs.

Lot Area ~½ Ac.

_____ Basement with Plumbing _____ Basement without Plumbing ✓ No Basement



Plot of System

Size of Tank Existing Gals.

Nitrification Field:
No. of Lines ~15'x60'
Sq. Ft. 900 + Linear Ft. 300'+
Depth of Stone in Lines 12"

Water Supply: Individual (✓)
Public ( )

Installed by Jason Benton

I understand and agree to install septic tank system as specified on this Improvements Permit.

Signed: _____

IMPROVEMENTS PERMIT BY JKH

COMMENTS: _____

CERTIFICATE OF COMPLETION BY JK Hinson, RS. DATE 4-14-89

EXISTING SYSTEM CHECKED BY: _____ DATE _____

CONSTRUCTION MUST COMPLY WITH ALL OTHER APPLICABLE STATE AND LOCAL REGULATIONS.

Permit is VOID if any unauthorized changes are made in installation of system and/or if any false information is supplied in making Improvements Permit.

Health Dept. Copy: White Inspection Dept. Copy: Yellow Sanitarian's Copy: Pink Owner's Copy: Gold