APPENDIX H

.DELL COUNTY HEALTH DEPARTMENT

SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: C.W. Bowen

DATE REQUESTED:

ADDRESS:

PLAT NO.:

COUNTY: Iredell

LOT SIZE:

LOCATION OF SITE: lot 8b Idlewood Harbor

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 6-8%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1 clay)	S (PS) U clayey	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U SBK	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) ~~PS~~ U 48+	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	(S) PS U 48+	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) PS U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U 80	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION*	P.S.			
SOIL SERIES	Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments:

Described By: DRH

Title:

Date: 6-16-81

DHS Form 2601 (2/77)
Sanitation